Page 1

Tuesday, June 28, 2011 9:58:40 AM Item ID: D3391-021 Accept Setup Start **Revision ID:** Stop Item Name: Fwd Tube Assembly **Start Date:** 6/28/2011 Start Qty: 1.00 **Cust Item ID:** Required Date: 7/28/2011 Reg'd Otv: 1.00 **Customer:** Reference: Start Run Process Plan: MF Date: 11-06-28 Tooling: Approvals: Date: Stop Date: SPC (Y/N): Date: Sequence ID/ Operation Accept Set Up/ Tool ID Reject Tool # Plan Ínsp. Reject Work Center ID Description **Run Hours** Code Qty Qty Number Stamp Draw Nbr **Revision Nbr** D3391 Rev H 100 0.00 Skidtubes Skidtubes 0.00 Memo Skidtubes Cut extrusion to 46.52 +0.010 -0.020 110 0.00 BENDING MACHINE - SKIDTUBES CNC Bend 1 0.00 CNC Delta 100 Bender Bend as per Dwg D3391 Using Bend Prog 3391021 QC5- Inspect part completeness to step on W/O 120 0.00

**Ouality Control** 

0.00

;		— - <del>-</del> -												
W/O:		WORK ORDER CHANGES												
DATE	STEP	PRO	CEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
-			. , , , , , , , , , , , , , , , , , , ,				<del> </del>			-				
Part No:		PAR #:	Fault Cat	egory:	NCF	R: Yes I	No DQA	٨:	_ Date: _					
	Resolution:				QA: N/C Closed: Date:									
NCR:			WORK ORDER NON-CONFORMANCE (NCR)											
DATE	STEP	Description of NC		ection B		Verific	ation	Approval	Approval					
	JILF	Section A	Initial Chief Eng	Action Description Chief Eng	iption Sign & Date					QC Inspector				
		·												
			1			٠.								
- ,														



Page 2

Tuesday, June 28, 2011 9:58:40 AM D3391-021 Item ID: Accept Setup Start **Revision ID:** Stop Item Name: Fwd Tube Assembly Start Qty: 1.00 6/28/2011 **Start Date: Cust Item ID:** Required Date: 7/28/2011 Req'd Qty: 1.00 **Customer:** Reference: Run Start Process Plan: Tooling: Date: Date: \_\_\_\_\_ Approvals: Stop Date: \_\_\_\_\_ SPC (Y/N): QC: Date: Sequence ID/ Tool # Plan Reject Operation Set Up/ Tool ID Accept Reject Insp. Work Center ID Description Code Qty Qty Number Stamp Run Hours 130 0.00 HAAS CNC VERTICAL MACHINING #1 0.00 HAAS I Memo 1-Machine as per Folio FA590 Rev. AA & Dwg D3391 Rev. HAAS CNC vertical machine #1 Identify as D3391-1 2-Deburr 140 QC2-Inspect parts off machine FAI/FAIB 0.00 0.00 QC Memo Quality Control 150 0.00

Mill Conv

Conventional Milling Machine

CONVENTIONAL MILLING MACHINE

0.00 Memo

Drill X1 Aft cap as per Dwg D3391 .1875" dia

A 1/04/29

W/O:	*	. :	V	VORK OF	RDER C	HANGES	*		*.		
DATE	STEP	PROC	EDURE CH	IANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			**************************************	<i>(</i>	,	S. v.			i.		
			•	•		· .				· · · · · · · · · · · · · · · · · · ·	
Part No:	<b>\</b>	PAR #:						No DQA			
NCR:						ORMANO					
DATE	STEP	Description of NC Section A	Initial Chief Eng		ve Action tion Desc Chief Eng	ription	Sign		ation on C	Approval Chief Eng	Approval QC inspector
			,						•		
<i>-</i> **			·	·						- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	

# Work Order ID 71313; Tuesday, June 28, 2011 9:58:40, AM



Page 3

Item ID:

D3391-021

Accept

Setup Start

Stop



**Revision ID:** 

Item Name:

Fwd Tube Assembly

**Start Date:** 

6/28/2011

OC:

Start Qty: 1.00

Required Date: 7/28/2011 Req'd Qty: 1.00



**Cust Item ID:** 

**Customer:** 

Tool ID

Reference:

Approvals:

Process Plan:

Date:

Tooling:

**SPC (Y/N):** 

Date:

Date:

Run

Accept

Qty

Start



Stop

Sequence ID/ Work Center ID

160

Quality Control

Operation Description

QC2- Inspect parts off machine FAI/FAIB

Date: \_\_\_\_\_

Set Up/ **Run Hours** 

0.00

0.00

Tool # Plan

Code

Reject Reject Qty Number

Stamp

Insp.

170

QC

Quality Control

QC8- Inspect parts - second check

Memo

Memo

0.00

0.00

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	CEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approvál QC Inspector				
									•				
				•									
		•						·					
Part No		PAR #:	Fault Cate	gory:	NCR: Yes No DQA: Date:								
	R	esolution:	QA: N/C Closed: Date:										
NCR:		ć.	WORK ORDER NON-CONFORMAN										
DATE	STEP	Description of NC			etion B	Verific	ation	Approval	Approvai				
DAIL	SILI	Section A	Initial Chief Eng	Action Description Chief Eng	iption Sign & Date		on C	Chief Eng	QC Inspector				
•				·									
			·	·									
į									l				
		<u>*</u>											
		*											
		· m-											

Page 4

Tuesday, June 28, 2011 9:58:40 AM D3391-021 Item ID: Accept Setup Start **Revision ID:** Stop Item Name: Fwd Tube Assembly **Start Date:** 6/28/2011 Start Oty: 1.00 **Cust Item ID:** Required Date: 7/28/2011 Req'd Oty: 1.00 **Customer:** Reference: Run Start Process Plan: Tooling: Approvals: Date: Date: Stop Date: QC: SPC (Y/N): Date: Sequence ID/ Operation **Tool ID** Set Up/ Tool # Plan Accept Reject Reject Insp. **Work Center ID** Description Code Oty **Qty** Number Stamp **Run Hours** 180 0.00 Skidtubes 1211, 1 Skidtubes 0.00 Memo Skidtubes 1-Drill float bag holes as per Dwg D3391 using DT8798(Do not open tow cap - Car holes to finish size) (ONLY DRILL HOLES MARKED "A") 2-Drill Remaining two holes for tow cap using DT 8819 Locating off of .1875" holes drilled in previous step SAN 11-06-30 3-Open tow cap holes to .208" as per Dwg D3391 4-Open Tow Ring hole to .640" as per Dwg D3391 5- open float bag holes 0.328" and counter sink as per dwg D3391 6-Deburr & Scribe Batch number Inside aft end. 7-Transfer drill D3391-021 with D3391-023 QC5- Inspect part completeness to step on W/O 0.00

Quality Control

Memo

Dait Aci		, <u></u>												
W/O:		WORK ORDER CHANGES												
DATE	STEP	PRO	CEDURE CH	IANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
				•										
					. j j									
Part No	•	PAR #:	_ Fault Ca	tegory:		NC	<b>R:</b> -Yes	No DQ	<b>A:</b>	Date: _	•			
<del></del>		esolution:	Disposition:				: N/C CI	osed:		Date: _				
NCR:		WORK ORDER NON-CONFORMANCE (NCR)												
DATE	STEP	Description of NC Section A	Initial Chief Eng		ve Action Seion Description Chief Eng	ection B	Sign &	Verific Secti		Approval Chief Eng	Approval QC Inspector			
					<u> </u>									
						10								
-										·				

Item ID:

D3391-021

Accept

Setup Start

Stop



**Revision ID:** 

Item Name: **Start Date:** 

Fwd Tube Assembly

6/28/2011

Start Qty: 1.00

**Req'd Qty:** 1.00



**Cust Item ID:** 

**Customer:** 

Reference:

**Approvals:** 

Process Plan:

Date:

Tooling:

Date:

Date:

Run

Start



Required Date: 7/28/2011

QC:

Date: SPC (Y/N):

Tool ID

Tool # Plan

Code

Qty

Accept Qty

Reject Reject

Insp. Number Stamp

**Work Center ID** 200

Sequence ID/

HandFinish

Hand Finishing

Operation Description

Chemical Conversion Coat per QSI005 4.1

**Run Hours** 0.00

Set Up/

0.00

SAD 11-05 30

210

Quality Control

QC3- Inspect Part Finish

Memo

Memo

0.00

0.00

220

Skidtubes

Skidtubes

Skidtubes

Memo

1-instal spacers as per dwg D3391 A/R Magnabond 6398 batch: M 1/6677

exp. date: // 8 cure time 12hrs. as per QSI015 2- grind crossbolt flush

3-back drill crossbolt if necessary

0.00

0.00

	12	- <del></del>										
W/O:			WC	RK ORDER CHANG	SES							
DATE	STEP	PRO	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
									•			
		·		•								
Part No	:	PAR #:	Fault Cate	gory:	_ NCR	: Yes N	No DQ	A:	_ Date: _			
	Resolution:		Disposition	1:	QA:	N/C Clo	sed:		Date:			
NCR:			WORK ORDER NON-CONFORMANCE (NCR)									
DATE	STEP	Description of NC		tion B	0: 0	Verific	ation	Approval	Approval			
DAIL	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti	on C	Chief Eng	QC Inspector		
								· ·				
					:							
		· · · · · · · · · · · · · · · · · · ·				<u>.</u>						
I	1		1		ı		1		1	I		

Page 6

Item ID:

D3391-021

Accept

Setup Start



**Revision ID:** 

Item Name:

Fwd Tube Assembly

Start Date:

6/28/2011

Start Qty: 1.00

**Req'd Qty:** 1.00 Required Date: 7/28/2011



**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Date:

Run

Start

Stop

Stop



QC:

Date:

SPC (Y/N):

Tool ID

Tool # Plan Code

Qty

Reject Accept Otv

Reject Number

Insp. Stamp

Work Center ID

230

Sequence ID/

Quality Control

Operation

Description

QC5- Inspect part completeness to step on W/O

Set Up/ Run Hours

Memo

235

HandFinish

Pressure Wash per QSI005 4.3

Memo

0.00

0.00

.....

Hand Finishing

AND REALODINE AS PER PAR09-043

240

Powdercoat

Powder Coating

White Gloss(Ref:4.3.5.1) per QSI005 4.3-Alum

0.00

START TIME: / L OVEN TEMPERATURE:

BL 11-7-4.

FINISH TIME:

		<del></del>											
W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
		•											
		· · · · · · · · · · · · · · · · · · ·	•	•									
						24. 2	\						
÷													
Part No		PAR #:	Fault Cate	gory:	NCR: Yes	No <b>DQ</b>	A:	Date: _					
Resolution:		olution:	Disposition	າ:	QA: N/C CI	osed:		Date: _					
NCR:			WORK ORDI	ER NON-CONFORM	IANCE (NCF	R)							
DATE	STEP	Description of NC Section A	Section A Initial Action Des			Verific Secti		Approval Chief Eng	Approval QC Inspector				
			Officer Errig	Chief Eng	Date								
	,			•									
							<u> </u>	·	1				
								·	·				
				•									
					ł								

#### Work Order ID 71313

Tuesday, June 28, 2011 9:58:40 AM



Page 7

Insp.

Stamp

D3391-021 Item ID: Accept Setup Start **Revision ID:** Stop Fwd Tube Assembly Item Name: **Start Date:** 6/28/2011 Start Qty: 1.00 **Cust Item ID:** Required Date: 7/28/2011 Req'd Qty: 1.00 **Customer:** Reference: Run Start Process Plan: Date: Tooling: Approvals: Date: Stop Date: SPC (Y/N): QC: Date: Sequence ID/ Operation Tool ID Tool # Plan Reject Reject Set Up/ Accept Work Center ID Description Qty Number Code **Qty** Run Hours QC3-Inspect Part Finish 250 0.00 Il 1107/06 0.00 Memo Quality Control 1 d III 1107/06 255 0.00 Skidtubes Skidtubes 0.00 Memo \*\*\*\* install D3591-1 spacer as per DSI9364 and wearplate and gasket as per Skidtubes DWG \*\*\*\* 257

Quality Control

QC5- Inspect part completeness to step on W/O

Memo

200 Suloslos

I, I

		— - <del>-</del> -											
W/O:			WORK ORDER CHANGES										
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
		PAR #:	Fault Cate	egory:	_ NCR: Ye	Date: _							
Res		esolution:	Disposition	on:	_ QA: N/C	Closed:		Date: _	<del></del>				
NCR:			WORK ORDER NON-CONFORMANCE (NCR)										
DATE	STEP	Description of NC		<del> </del>	tion B	Verif	ication		Approval				
	JILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sig Da	Section C		Chief Eng ,	QC:Inspector				
								ļ					
!					1			1	1				

#### Work Order ID 71313

Tuesday, June 28, 2011 9:58:40 AM



Page 8

Item ID:

D3391-021

Accept

Setup Start

Stop



**Revision ID:** 

Item Name:

Fwd Tube Assembly

**Start Date:** 

6/28/2011

Start Qty: 1.00

Required Date: 7/28/2011

Req'd Qty: 1.00



**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

QC:

Process Plan:

Operation

Description

Date:

Date:

**Tooling:** SPC (Y/N): Date:

Tool ID

Run

Stop



Sequence ID/

**Work Center ID** 

260

Packaging Packaging

Memo

Memo

Set Up/

**Run Hours** 

0.00 pd 12-742-013/B71323

Code

Tool # Plan

Date:

Accept Qty

Reject Reject Qty Number

Insp. Stamp

280

QC21- Final Inspection - Work Order Release

0.00

0.00



Quality Control

Identify as per dwg & Stock Location: W/O

0.00

11/7/11/12) ME 11-07-07

	•								
W/O:		2	WC	RK ORDER CHANGI	ES				
DATE	STEP	PRO	OCEDURE CHA	- <del> </del>	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								·	
						····			
				·					
		·							
Part No	: <u> </u>	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date: _	
		Resolution: Disposition: QA: N/C C							
NCR:			WORK ORDI	R NON-CONFORMA	NCE (NCI	7)			·
DATE	STEP	Description of NC	Corrective Action Section		Verific	ation	Approval	Approval	
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Secti		Chief Eng	QC Inspector
							,		
				•					
1	1				I	I		I	1

#### **Picklist Print**

Tuesday, June 28, 2011 9:58:37 AM

Work Order ID: 71313

Parent Item:

D3391-021

Parent Item Name: Fwd Tube Assembly



Start Date: 6/28/2011

Required Date: 7/28/2011

Start Qty: 1.00

Required Qty: 1.00

Comments:

IPP A□05.09.13□New issue□

KJ/JLM□

IPP B□06.02.10□Dwg rev.D ecn 773 □EC□ IPP C□06.05.02□Added inspections □EC□

IPP D 07.03.13 rev F dwg

EC EC verified by: DD

IPP E 07.11.07 revG dwg ecn1053P

IPP Rev:f ECN 1056 07-11-12 DD verified by: EC

IPP Rev:G 08-09-08 new process (ecn 08-510) DD verified by:EC

IPP Rev:H 08-09-10 revH as per dwg DD verified by:EC

IPP Rev J 09.02.02 added hardware EC verifified by: DD

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D6013-047		Manufactured	No			100	Each	18.0000	1    <b>    </b>	1			
·				Location LG	26547	Loc Q	18 18	Loc Code		)		),,	6-28
D3670-4-200		Manufactured	No			220	Each	38.0000	4	4			Dh.
				<u>Location</u> LG	70822	<u>Loc Q</u>	38 38	Loc Code	_	4	_		u louf zi
D3401-041  Tow Cap Assembly	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Manufactured	No	`		255	Each	2.0000	1	1 M	1107	(04	
, -				Location FP007	<u>6150</u> 5	<u>Loc C</u>	2 2	Loc Code	_	χι	_ _		

W/O:			WO	RK ORDER CHANG	ES					
DATE	STEP	PR	OCEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		•							,	
Part No	•	PAR #:	Fault Categ	jory:	_ NCR	: Yes	No <b>DQ</b>	A:	Date:	
			Disposition	:	_ QA:	N/C CI	osed:		Date: _	
NCR:			WORK ORDER NON-CONFORMANCE (NCR)							
DATE	STEP	Description of NC Section A	Initial Action Descri		on B	Sign &	Verific Secti	cation on C	Approval Chief Eng	Approval QC inspector
			Office Eng	Office Eng		Date				
					-					
		·				· · · · · · · · · · · · · · · · · · ·				

#### **Picklist Print**

Tuesday, June 28, 2011 9:58:37 AM

Page 2

Work Order ID: 71313 Parent Item: D3391-021 Parent Item Name: Fwd Tube Assembly Required Date: 7/28/2011 Start Date: 6/28/2011 Start Qty: 1.00 Required Qty: 1.00 D3564-13 Manufactured No 255 Each 16.0000 1107/06 Wearshoe Location Loc Qty Loc Code FP016 16 16 69280 D3566-13 255 26.0000 Manufactured No Each 107/06 Gasket Location Loc Qty Loc Code FP 24 69281 24 FP014 2 68341 2 NAS1149C0332 255 AN960C10L Purchased No Each 0.0000 10 . 10 117460 4/07/06 610 washer AN3C4A 255 2,162.000 Purchased No Each **BOLT** Location Loc Qty Loc Code ST350 2162 117313 2 117688 776 117795 500 117872 22 500 118012 XIO 118112 362

W/O:		WORK ORDER CHANGES												
DATE	STEP	PRO	OCEDURE CHAI	NGE		Ву	Date	Qty	Approvai Chief Eng / Prod Mgr	Approval QC Inspector				
			<del>-</del> .				•							
							<del></del>							
									:					
Part No	•	PAR #:	Fault Cate	gory:	_ NCR	l: Yes I	10 DQ	A:	_ Date: _	· .				
Resolution:														
NCR:			WORK ORDER NON-CONFORMANCE (NCR)											
DATE	STEP	Description of NC Corrective Actio						ation	Approval	Approval				
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti	on C	Chief Eng	QC Inspector				
								•	:					
								*	•					
	·													
	1	,					1							

#### **Picklist Print**

Tuesday, June 28, 2011 9:58:38 AM

Page 3

Work Order ID: 71313

D3391-021

Location

Parent Item:

Parent Item Name: Fwd Tube Assembly

Start Date: 6/28/2011

Required Date: 7/28/2011

Start Qty: 1.00

Required Qty: 1.00

D3672-1

Manufactured No 255

Loc Qty

Each

1,122.000

Loc Code

Vd

10

Phenolic Washer

		255	Each	0.0000
	52505		26	
ST077	$\leq \epsilon_{\rm c}$		26	
	66821		500	
	.64177		596	
ST074		1	1096	

255

AELS-1032-130 Purchased

**INSERT** 

AELS-1032-225

Purchased

No

No

KN 117717

11117717

Each

0.0000

10

**INSERT** 

W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		-							
Part No	•	PAR #:	Fault Cate	gory:	NCR: Yes	No <b>DQ</b>	A:	_ Date: _	
Resolution:		esolution:	Dispositio	n:	_ QA: N/C CI	osed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORMA	ANCE (NCR	) -			
DATE	STEP	Description of NC			Section B Veri		ation	Approval	Approval
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti	on C	Chief Eng	QC Inspector
								-	
							•		
					į				


DART AEROSPACE LTD	Work Order:	71313
Description: Float Skidtube (412)	Part Number:	D3391-1
•		
Inspection Dwg: D3391 Rev: H		Page 1 of 1

#### FIRST ARTICLE INSPECTION CHECKLIST


Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
0.687	+0.010/-0.000	0.692	~		Vern	6A-01
3.590	+0.025/-0.010	3.615	~		Mic	GA-10
3.300	+0.040/-0.000	3.340			Vern	6A-01
1.429	+0.040/-0.060	1.421	~		11	11
4.250	+/-0.010	4.250	~		11	11
4.250	+/-0.010	4.250	_		1(	11
<del>-0.500-</del>	<del>-+/-0:010</del>					
,500	±.010	,501			RA 26	Wirn
0.1875	±.010 +.004	, 187			"	4
***						447
				1		

Measured by:	1. A SA	Audited by:	Preliminary Approval:	
Date:	11/06/29 1/06/	Date: 11.02.79	Date:	


Rev	Date	Change	Revised by	Approved
Α	06.04.27	New Issue P/O D3391-011/-021	KJ/JLM	
В	06.06.19	Tolerances revised per D3391 Rev. E	KJ/JLM	
С	07.03.21	Dimensions removed per Dwg rev. F	KJ/JLM	
D	07.11.23	Dwg Rev. updated	KJ/EC/DD	
E	09.12.14	Dwg Rev updated	KJ in	
F	11.06.21	Dimension 0.500 added	KJ 947-	




W/O:			W	ORK ORDER CHANGI	ES				
DATE	STEP	PRO	CEDURE CH		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								7 Tod Wgi	
						<del>-</del>			
4									
Part No	:	PAR #:	Fault Cat	egory:	NCR: Yes	No DQ	A:	Date:	
	R	esolution:	Dispositi	on:	_ QA: N/C C	losed:		Date: _	<del></del>
NCR:		V	VORK ORI	DER NON-CONFORMA	NCE (NCI	₹)			
DATE	OTED	Description of NC Corrective Action			on B	Verifi	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sec	tion C	Chief Eng	QC inspector
								1	
		i 							
-									




Dail Aci	ospace	Elu								О
W/O:			WO	RK ORDER CHAN	GES	, · ·		, ,		······································
DATE	STEP	PRO	OCEDURE CHAN	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						-	,			
								·		
Part No		PAR #:								
Resolution:		esolution:	Disposition	1:	QA:	N/C Clos	sed:		Date: _	
NCR:			WORK ORDE	ER NON-CONFORM	MANCE	(NCR)				
DATE	STEP	Description of NC	Initial	Corrective Action Se Action Description	ection B	Sign &	Verific		Approval	Approval
		Section A	Chief Eng	Chief Eng	•	Date	Section	on C	Chief Eng	QC Inspector
		•								
	· · · · · · · · · · · · · · · · · · ·									




	•								
W/O:		****	WO	RK ORDER CHANG	GES			***************************************	· · · · · · · · · · · · · · · · · · ·
DATE	STEP	PRO	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Categ	ory:	NCR: Yes	No DQ	A:	Date: _	
	Re	esolution:	Disposition	:	QA: N/C CI	osed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NCF	₹)			
DATE	STEP	Description of NC			tion B	Verific	cation	Approval	Approval
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date		ion C	Chief Eng	QC Inspector
									:




W/O:			WC	RK ORDER CHANG	GES			,	
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	·	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	A:	_ Date: _	
Res		esolution:	Disposition	n:	QA: N/C CI	osed:		Date: _	<del></del>
NCR:		,	WORK ORDI	ER NON-CONFORM	ANCE (NCF	R)			
DATE	STEP	Description of NC			tion B	Verific		Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti	on C	Chief Eng	QC Inspector
								:	




	•			· ·					•
W/O:			W	ORK ORDER CHANGE	ES				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
<del> </del>									
				·					
Part No	•	PAR #:	Fault Cate	gory:	NCR: Yes	s No DQ	A:	_ Date: _	<del></del>
		esolution:						Date: _	
NCR:	-		WORK ORD	ER NON-CONFORMA	NCE (NC	R)			
DATE	STEP	Description of NC	Corrective Action Section B				cation	Approval	Approval
		Section A	Chief Eng	Action Description Chief Eng	Sigr Dat		tion C	Chief Eng	QC Inspector
							•		



	•								•
W/O:			WC	ORK ORDER CHANC	GES			-	
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						· · · · · · · ·			
Part No		PAR #:							
		esolution:						Date: _	
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NC	R)			
DATE	STEP	Description of NC	Corrective Action S Initial Action Descriptio		tion B		cation	Approval	Approval
		Section A	Chief Eng	Chief Eng			ion C	Chief Eng	QC inspector
-							·		
l									



W/O:			W	ORK ORDER CHANG	GES				*
DATE	STEP	PRO	OCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							-		;
•		PAR #:	Fault Cate	egory:	NCR: Yes	No DQ			
	Re	esolution:	Disposition	on:	QA: N/C	Closed:		Date: _	······
NCR:		,	WORK ORD	ER NON-CONFORM	ANCE (NC	R)			
DATE	STEP	Description of NC	1	Corrective Action   Section   Initial   Action Description			cation	Approval	Approval
		Section A	Chief Eng	Chief Eng	Sign Dat		tion C	Chief Eng	QC Inspector
			.						
	;								
									:



Dail Mei USpace Liu	Aerospace	<b>Ltd</b>
---------------------	-----------	------------

	•									
W/O:			W	ORK ORDER CHANG	GES					
DATE	STEP	PRO	PROCEDURE CHANGE					Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				·						
			4.500							
Part No	•	PAR #:	Fault Cate	gory:	NCR: \	es N	o <b>DQ</b>	A:	_ Date: _	
	Re	esolution:	Disposition: Q			QA: N/C Closed: Da				
NCR:			WORK ORD	ER NON-CONFORM	ANCE (N	ICR)				
DATE	STEP	Description of NC		ction B		Verification		Approval	Approval	
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng		gn & Date	Secti	on C	Chief Eng	QC Inspector
									·	
				,						
			1 1		1		1		1	1

DRAWING	NO.	TITLE		REV. H	DART A	EROSPAC	E USA, INC D.E.	O. NO.	SHEET NO.	SCALE
D3391		412 FLOAT	SKIDTUBE	ı	ENG	<b>INEERING</b>	ORDER D33	391-H-1	SHEET 1 OF, 1	NTS
DRAWN	Ú.	7	CHECKED	ļ,	MFG. AF	PR.	APPRO\	ED MA	DE APPR.	
DATE	09.09	.23	DATE	04.04.24	DATE	09/09/	2S DATE	09/09/30	DATE 09/09	30

#### **PURPOSE:**

LPS-3 IS NO LONGER USED DURING ASSEMBLY OF D3391-041/-043 SKIDTUBES.

#### **CHANGE:**

AMEND NOTE 2 OF D3391-041/-043 SKIDTUBE ASSEMBLIES (ZN A6-1, A6-2) AS FOLLOWS:

2) SPRAY INSIDE OF TUBE WITH A COAT OF LPS LABORATORIES "LPS-3" AFTER FINISH-AND AFTER INSTALLATION OF INSERTS. COAT ALL EXPOSED FASTENERS WITH LPS LABORATORIES "LPS PROCYON" AFTER FINAL ASSEMBLY, CLEAN EXCESS OFF POWDER COATING WITH MEK DEGREASER.



AMP.

\*1/3/2

Dart Aerospace	Ltd	
----------------	-----	--

	•			·						
W/O:			WC	ORK ORE	ER CHANGES			.,	• • ·	
DATE	STEP	PROCEDURE CHANGE			•.	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							-			
				•	•				198 2 <b>3</b> * 1	•
			e.							
Part No:		PAR #:	Fault Cate	gory:	Ņ.	CR: Yes	No DQ	A:	_ Date: _	
	R	esolution:	Dispositio	Disposition: C			QA: N/C Closed: Date			
NCR:			WORK ORD	ER NON-	CONFORMANC	E (NCR	<b>(1)</b>			
DATE	STEP	Description of NC	Corrective Action Se				Verific	erification	Approval	Approval
DAIL	SILI	Section A	Initial Chief Eng	Actio	n Description Chief Eng	Sign & Date	Sect	ion C	Chief Eng	QC Inspector
,								•		
					Ì					
<del>**</del> ***										
*%						No.			, dag o	
***										